ENGINEERING CHANGE NOTICE

		*			
DART AEROSPACE LTD Date: 07.01.24		Amendment Design Review (ADR) Yes	ECN #:	907	
		ADR Date: 07.01.22 07.04.02			
Job No: 00075		Created By: (1), Checked By:	QH-	a	
Product No: D412-630		Approved By: Approved By:		AV	
Product Name: Heli-Access-Step		(Proj. Manager) (Management	: if reqd)	MY	
Documents Affected:				VI	
Release:	Supercede:				
- D3560 Rev. B	- D3560 Rev.A				
- D3562 Rev. B	- D3562 Rev.A				

# Engineering Actions	Yes	No	Responsible	To happen by:	Complete
1 Required Documents/Drawings Under Review?	X		CP	ASH	07.05.09
Update Blue/Pink Folder/Electronic File		Х			
3 Update DSI Folder/Electronic File		Х			
4 Update D-Part Master Binder	X		KJ	ASAP	07.05.09
5 Update Grey Project Binder	Х		CP	ASAP	67.67.104
6 Update DEO/DSI Binder		Х			<u> </u>
7 Update Master Document List (MDL)	Х		СР	ASA-P_	11 02,05.09
8 Update Document Record (DR)	Χ		CP	MAP	\$ 57,05.09
9 Update Change Record Form	Х		CP	ASAL .	\$ 07.05.05
0 Move Electronic File	Χ		KJ	ASAP.	07.05.09 to
11 Notify TC of Change		Х			0
12 Notify FAA of Change		Х			
3 Update QSI 021 (TC/FAA STC)		Х			
4 Update QSI 036 (K-Kits)		Х			
5 Update Accpac Database	Х		KJ	ASAY	07,05,09
6 Update Access Database	×		长女	BAP.	07.05.09
7 Verification ARC		Х			0_
8 Update STC Approval List		Х			
19 Update Product Development Summary	Х		CP/ SSIF	ASAP	161.66.U6 U
20 Create/Update COSS (Estimate/BOM)	Х		JLM/EC 🗸	ASAP.	(1/07 da 03
21 Create/Update PPP's	Х		KJ	A3AP.	67.05.09 47
22 Update Paperwork Kits in Production		Х			
23 Update Paperwork Kits in Stock		Х			
24 Red Tag Stock with old CHG #		Х			
Rework/Scrap Current Production		X			
Rework/Scrap Kits in Stock?	X	111	1-1-	BAP.	07.06.08 there
7 Update Qpulse/Laminated Dwgs		X			0
28 Create/Update Controlled PDF Files	Х		KJ	ARAP.	07,05,09 9
29 Create/Update FAI sheets	Х		JLM/EC	BH	
O Create/Update CNC Programs	Х		JLM/EC	ASAP	2/1/07.00
31 Create/Update Tooling	Х		JLM/EC	13H. (- 10/01/0°
MPP required?		Х			/ /
3 Notify Previous Customers		Х			
Notify Eurocopter France		Х			
35					
86					

Description / Action:

- D3592 Rev.A

- -D3562-041/-042 Step Weldment now a rivited design.
- -D3560-1/-2/-3/-4 Arm, shape has changed
- -D3560-041/-042/-043/-044 Arm Weldment, new parts made from welding D3560-1/-2/-3/-4 Arm with D3592-1 Plate. Need weld jig for attaching D3592-1 Plate at 2.4 degree angle
- -D3592-1 Plate, new part. Will need special jig to bend plate into shape to match D2622
- -D412-630-033/-034 kits are now at CHG # 002, pick lists for these kits are not affected
- -Need to make qty(1) D3562-041 or -042 Step Weldment as prototype to verify design and tooling DONE OK GOT.65.69 REWEK ANY -033/-034 KITS IN STUCK WINEW D356Z WELDMENT

- Vermork	אמו א	033/2079	V112 TY	2 210ck MI WEN	7 300C W CUIIII	E 14		-
	7			ECN Complete:	#	Date:	07.06.30	

AMENDMENT DESIGN REVIEW (ADR)

Part/Installation No.:	D412-630	Rev:	Design Review No.:	Date: 07.04.02
Project Number:	00075		Project Description/Title:	Heli-Access-Step
•			•	(Folding Step)
Eng. Project Manager:	Chris Provencal			

Persons Present	Title	Initial	
	Design Manager		
Chris Provencal	Engineering Project Manager	q'	
David Shepherd	Chief Engineer (DE #02)	-#	
	Manufacturing Manager	Va	
	Quality Manager		

Comments

- -Customer complained about several cracked steps. Checking steps In stock found a brand new step with a cracked weld.
- -Problem determined to be cracking of the weld during manufacture, step extrusion material is clearly warping from welding.
- -D412-630-033/-034 steps were revised to address this problem
- -determined that welding the D3560 Arms onto a thicker plate (0.125") instead of step should prevent cracking problem. This plate will then be rivited to the step extrusion
- -Good fit is required between 0.125" plate and D3560 arm. Plate that is welded to D3560 Arms will have to be secured to prevent it from warping.
- -sikaflex will be placed between the new arm weldment and the step extrusion to reduce stress levels -welding jig required to ensure plate welded on at 2.4 degrees.
- -(07.04.02) Testing of the step design indicated that the D3560-X Step Arms are not strong enough for the loading specified in SR-P577-1. At 990 lb, observed buckling on the side of the thru-pocket under compression. At 1188 lbs the side in tension snapped. Analysis was not done correctly, part was modeled as one section. Thru-pocketing prevented transfer of loads thru section. Should have considered 2 individual sections.
- -(07.04.09) D3560-X redesigned with pocketing instead of thru-holes, similar to original step arm design.
- -(07.04.24) Redesigned pocketed D3560-X withstood 1530 lb (ref attached pics) and is acceptable.

Key Tasks (Check or N/A)	Check	Responsible	Completion Date
Review Outstanding TSR/NCR/CAR/PAR	Y:	CP	
Fill out Criteria/Constraints Form – Inputs	N	N/A	
Fill out Project Evaluation Form	N	N/A	
D-Part creation/revision	Y	CP	
Get Manufacturing Input	Y	СР	
First Article Inspection	Y	СР	
Fit and Function Test	. Y	СР	
Structural Test	Y	СР	
Reports (Compliance, Loads, Stress, Conformity, DSI)	N	N/A	
Check Drawings against all QSIs	Y	СР	
Review Criteria/Constraints Form	N	N/A	
Revision to existing approval	" N	N/A	
Close Amendment Project	Y	CP	
Conclusion:	The same of the sa	· · · · · · · · · · · · · · · · · · ·	

Conclusion:

Procede with design change, ref ECN #907

ENGINEERING CHANGE NOTICE

mpp

DART AEROSPACE LTD			Amendment Design Rev	/iew (ADR) Yes/No: V	I-du " 007		
Date: 07.01.24		ADR Date: 07.01.2	- F€N #: 907				
Job No: 00075		Created By: 💋	Checked By:				
Product No: D412-630			Approved By:	Approved By:			
Product Name: Heli-Access-Step		(Proj. Manager)	(Management if reqd)				
Documents Affected:			N. Toj. Managory	<u> </u>			
Release: Supercede:							
- D3560 Rev. B - D3560 Rev.A							
- D3562 Rev. B - D3562 Rev.A							
- D3592 Rev.A							
# Engineering Actions	Yes	No	Responsible	To happen by:	Complete		
1 Required Documents/Drawings Under Review?	X		СР		11 07.05.09		
2 Update Blue/Pink Folder/Electronic File		Х					
3 Update DSI Folder/Electronic File		Х			1		
4 Update D-Part Master Binder	Х	ļ	KJ		07.05.094		
5 Update Grey Project Binder	Х	<u> </u>	СР				
6 Update DEO/DSI Binder	<u> </u>	X	1				
7 Update Master Document List (MDL)	Х		CP		1 02.05.09		
8 Update Document Record (DR)	Х		CP		107,05.09		
9 Update Change Record Form	Х		СР		607.65.05		
10 Move Electronic File	Х	1	KJ	VIII.8	07.05.09 10		
11 Notify TC of Change		X			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
12 Notify FAA of Change		Х					
13 Update QSI 021 (TC/FAA STC)	<u> </u>	Х			<u> </u>		
14 Update QSI 036 (K-Kits)	-	X			<u> </u>		
15 Update Accpac Database	X	 ^	KJ		07.05.09		
16 Update Access Database	×		长女		11733		
17 Verification ARC	_^	X	42		07.05.09		
18 Update STC Approval List		X			<u> </u>		
19 Update Product Development Summary	\vdash	 ^-	CD/Dek				
	X		CP/88#				
20 Create/Update COSS (Estimate/BOM)	Х		JLM/EC V				
21 Create/Update PPP's	X	ļ	KJ	<u>.</u>	07.05.09 4		
22 Update Paperwork Kits in Production		Х					
23 Update Paperwork Kits in Stock		Х					
24 Red Tag Stock with old CHG #		Х					
25 Rework/Scrap Current Production		X					
26 Rework/Scrap Kits in Stock?	X	111		/	V AFUOURS 31.		
27 Update Qpulse/Laminated Dwgs		Χ ~					
28 Create/Update Controlled PDF Files	Х		KJ		07,05.09 9		
29 Create/Update FAI sheets	Х		JLM/EC		1 0		
30 Create/Update CNC Programs	Х		JLM/EC				
31 Create/Update Tooling	X		JLM/EC				
32 MPP required?		Х					
33 Notify Previous Customers		Х	. •				
34 Notify Eurocopter France		X					
35		<u> </u>					
36		1			 		
Description / Action:					<u> </u>		
-D3562-041/-042 Step Weldment now a rivited design	an.		to the state of th				
-D3560-1/-2/-3/-4 Arm, shape has changed	911.		1 m	•			
-D3560-041/-042/-043/-044 Arm Weldment, new parts made from welding D3560-1/-2/-3/-4 Arm with D3592-1 Plate. Need weld jig for							
attaching D3592-1 Plate at 2.4 degree angle							
D3592-1 Plate, new part. Will need special jig to bend plate into shape to match D2622							
D412-630-033/-034 kits are now at CHG # 002, pie Need to make gty(1) D3562-041 or -042 Step Weld * Kewek Aby -033/-034 Kits i	ment a	as proto	type to verify design and	tooling - DONE OK	CP07.05.0911 1		
REWORK ANY -033/-034 KING 1	N <	MOK	W/ NEW DRSKT	LUELDINENT	1 He Liment		
				<u> </u>	Well The		
2+ 14			ECN Complete:	Date:	IN A lake		
W.C. (C.					L VI V DMI		